Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

GZ1007 VAULT 1814 NY Spills S111836402 WSW W 37TH ST AND SURF AVE N/A

> 1 BROOKLYN, NY

1.324 mi.

6990 ft. Site 2 of 5 in cluster GZ

Relative: SPILLS:
Higher Name: VAULT 1814

Actual: Address: W 37TH ST AND SURF AVE

0 ft. City,State,Zip: BROOKLYN, NY Spill Number/Closed Date: 1201654 / 2012-07-19

 Facility ID:
 1201654

 Facility Type:
 ER

 DER Facility ID:
 418771

 Site ID:
 464376

 DEC Region:
 2

Spill Cause: Equipment Failure

Spill Class: C4 2401 SWIS: Spill Date: 2012-05-21 Investigator: **RWAUSTIN** Referred To: Not reported Reported to Dept: 2012-05-21 CID: Not reported Water Affected: Not reported

Spill Source: Commercial/Industrial

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2012-05-21
Spill Record Last Update: 2012-07-19
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT

DEC Memo: "7/19/12 - Austin - 5 gals transformer fluid atop 300 gals water in

transformer vault - Con Ed contained and cleaned up the spill - See $\,$

eDocs for further information - Spill closed - end"

Remarks: "Caller advised 5 gallons of oil spilled into 300 gallons of water in

the vault which is contained. Clean up is pending."

All Materials:

Site ID: 464376 Operable Unit ID: 1214429 Operable Unit: 01 Material ID: 2212471 Material Code: 0020A Material Name: transformer oil Case No .: Not reported Material FA: Petroleum Quantity: 5.00 Units: G

Recovered: Not reported Oxygenate: Not reported